BRUHAT BANGALORE MAHANGARA PALIKE

Inspection Report

1	Name Of Work:	Construction of Terrace Floor Building at JP park Swimming Pool Parking area in ward no 17
2	Administration Approval & Date	JC/RRN/AS/2759/2013-14 Dtd: 18.01.2014
3	Technical Sanction Estimate No. & Date	Modified TS: CE/RRN/TS/113/2016-17 Dtd: 28.06.2016
4	Estimate Amount	19,96,000/-
5	Job Code No.	017-14-000064
6	P-Code	P-2434 Development works for Bangalore City
7	Agreement No and Date:	EE/RRND/Agmt/275/13-14 Dtd: 22.02.2014
8	Work order Number & Date	EE/RRND/WO/275/13-14 Dtd: 22.02.2014
9	Contract Amount as per Agreement	Rs. 20,45,878/-
10	Bill Amount	Rs. 19,01,165/-
11	B.R No. & Date	154/16-17 Dtd: 28.09.2016
12	Agency	M/s Vrushabhadri Constructions
13	M.B. Number & Page No. of Measurement records	3923/15-16 Page No 392230 to 392234
14	Date of Inspection	14.09.2017
15	Enclosures	& Number of photos taken during inspection
16	I have Inspected the Conserned person, as PR/414/A/17-18 Inspection Report -ments of the Items which are Susceptible for measurements have been Checked and found to be satisfactory	above site Location along with the per EE (RRND) Letter No EE/RRN/ Dated 1-9-2017. The measure- indicated in the MB/XL Sheets

EE (RRN) Division, RR Nagara Zone.

ರಾಜರಾಜೇಶ್ವರಿ ನಗರ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು-560 072

14/9/2017
(R. Sathyanarayana)
Inspection Report Officer.

Scanned by CamScanner